



THE HARTFORD STEAM BOILER
INSPECTION and INSURANCE COMPANY
HARTFORD • CONNECTICUT 06102

BALTIMORE OFFICE—SUITE 200, 401 WASHINGTON AVENUE, TOWSON, MARYLAND 21204—(301) 296-0580
5/22/78 FROM WASHINGTON, D.C. (202) 347-0047

United Evangelical Church
923-943 S. East Ave.
Baltimore, Md. 21224

The following equipment located at 923-943 and rear 945 S. East Ave., Baltimore, Md. was examined by Inspector G. Babb on 5/01/78 and the conditions noted should receive attention as indicated.

Elec. Wtr. Htr. No. WP6928

The safety valve discharge pipe has been reduced in pipe size from 3/4" to 1/2". This reduction in the outlet from the valve reduces the relieving capacity accordingly. We recommend the discharge pipe be run full size from the safety valve to the point of discharge.

The condition outlined was discussed with Mr. Wolfeman, Maint., at the time of inspection.

Inspection of other equipment disclosed no conditions that require attention at this time.

Yours very truly,

A handwritten signature in blue ink that reads "W. H. Caulberg". The signature is written in a cursive, flowing style.

W. H. Caulberg,
Supervising Inspector.

WHC/plm/87

C: John G. Rolker, Inc.
211 Keyser Bldg.
Calvert & Redwood Sts.
Baltimore, Md. 21202

This report does not purport to set forth all hazards nor to indicate that other hazards do not exist. By issuing this report, neither the Company nor any of its employees makes any warranty, express or implied, concerning the object (objects) described in this report. Furthermore, neither the Company nor any of its employees shall be liable in any manner (other than any liability that may be expressed in any policy of insurance that may be issued by the Company) for personal injury or property damage or loss of any kind arising from or connected with this inspection or failure to inspect.
