

TITLE	John R. Frazier, Bureau Chief
AGENCY NAME & ADDRESS	Fire Prevention and Investigation Bureau 414 N. Calvert Street - 21202
SUBJECT	Parents and Children Together 3200 Dillon Street - 21224

CITY OF
BALTIMORE
MEMO



DATE: August 3, 1994

TO
Ms. Lillian Augustus, Director
Office of Child Care Licensing
and Regulations, Region No. II
2701 N. Charles Street, 3rd. Fl.
Baltimore, Maryland 21218

(X) At your request, Fire Inspector Yvette Stanley of the Fire Prevention Bureau conducted an inspection on August 2, 1994 of the subject premises - a 4 story, non sprinklered building of ordinary construction and currently occupied as a Church.

() Be advised, _____ of the Fire Prevention Bureau conducted a reinspection on _____ of the subject premises as follow-up to the original inspection conducted on _____.

FOR THE PURPOSE OF A DAY CARE CENTER/NURSERY SCHOOL LICENSE:

(X) Issuance () Renewal (X) Preliminary Inspection () Final Inspection
() Capacity _____ () Capacity Increase from _____ to _____

REPORT:

- () There were no violations of the BOCA Fire Prevention Code or the NFPA 101 Life Safety Code noted at the time of inspection.
- () The following BOCA Fire Prevention Code violations were noted at the time of inspection.
- (X) The following NFPA 101 Life Safety Code violations were noted at the time of inspection.
- () Statement other than or in addition to above.

10-7.3.4.1 - Smoke detectors must be hard wired and interconnected into the Fire Alarm System with pull stations at every exit no more than 5 feet from exit.

10-7.2.9 - First and second floors emergency lighting with battery back-up on stairwells shall be installed in stairs and corridors.

10-2.8. Means of egress shall be illuminated as follows:

1. Two illuminated exit signs inside of school area (2nd floor).
2. Two illuminated exit signs inside of play area (first floor).
3. Illuminated signs shall be of the battery back-up type.



Region II

Child Care Administration

2701 N. Charles Street - Third Floor
Baltimore, Maryland 21218
(410) 554-0457

8/8/94

RE: *Parents, Children
Fogelstein*

Dear Director:

Enclosed are copies of recent reports made by inspectors of the Baltimore City Fire Department. You will note that recommendations have been made by *Inspector Yvette Stanley*.

Violations of regulations listed on the inspection report must be corrected before a license to operate is issued. Please submit to me, in writing, a plan of correction for all violations noted in the inspection report, giving specific dates when violations were or will be corrected. The plan of correction must be submitted within two weeks after receipt of this inspection report. When I receive that letter, a request for reinspection will be made.

Should you have any questions, please call me at 554-0473.

Sincerely,

Jvis Hurty
Licensing Specialist

Enclosures

4/94

TO: J. Talagsen, Property Committee Chair

FROM: Pastor

DATE: 8-10-94

SUBJECT: PACT

Attached you will find the report from the Fire Department for you information and action.

Let me know if I can be of further assistance.

cc: G. Hammerbacher
C. Clark
H. Jacob