

OFFICE  
728-7768

HOME  
795-2824

**Robert A. Miller**  
**Stained Glass Studio**  
ART LEADED AND STAINED GLASS

855 NORTH HOWARD STREET  
BALTIMORE, MD. 21201

**Robert C Murphy Jr**  
Adjuster

**GAB**

GAB Business Services Inc  
6305 York Road  
Baltimore Maryland 21212  
Tel 301 - 433-9220

*Est Rabbiner Rep - 12/7/78*

designed-installed-repaired



Smiths' Stained  
Glass

Norman Smith  
423 Kenneth Square  
Balto. Md. 21212 323-6079

Bernard Smith  
2800 Hanson Ave.  
Balto. Md. 21209 764-6738

FIRST CLASS  
PERMIT NO. 43  
WINONA, MINN.



**BUSINESS  
REPLY  
MAIL**

**No Postage Stamp Necessary if Mailed in the United States**

**POSTAGE WILL BE PAID BY  
HAUSER STUDIOS OF STAINED GLASS  
1171 MANKATO AVENUE  
WINONA, MINNESOTA 55987**



## ROBERT A. MILLER STAINED GLASS STUDIO

Memorial Windows a Specialty

Opalescent : : Antique Glass  
Windows Restored

. . . Art Leaded Glass . . .

855 NORTH HOWARD STREET  
BALTIMORE, MARYLAND 21201

Ecclesiastical and Domestic

Stained and Mosaic Glass  
Tiffany Shades Repaired

January 9, 1979


United Evangelical United Church of Christ  
East And Dillon Streets  
Baltimore, Maryland 21224

This is an estimate to replace four broken pieces of painted  
glass in figure window.

This work can be completed for the sum of \$ 640.00.

This estimate does not include storm glass.

Sincerely,



Robert A. Miller

East Ave. & Dillon St.  
Baltimore, Md. 21224.  
April 27, 1979.

ROBERT C. MURPHY, JR. - Adjustor  
GAB Business Services, Inc.  
6305 York Road  
Baltimore, Md. 21212.

Dear Mr. Murphy,

Enclosed are photocopies as follows:

1. Proposal from Art Craft, 16908 York Rd., Hereford, Monkton P.O., Md. 21111 in the amount of \$513.85 for repairing our stained glass window broken by your insured.
2. Proposal from Robert A. Miller Stained Glass Studio, 855 North Howard St., Baltimore, Md. 21201 in the amount of \$640.00 for repairing the same window but not including the protective storm window.

The lower estimate by Art Glass Crafters includes the repair of the storm window.

We would, therefore, appreciate your sending your check to the order of our Church to compensate us for the window broken by your insured.

Thank you very much.

Yours respectfully,

G.A.T., Jr./a  
Encl. (2)

\_\_\_\_\_  
Church Council  
United Evangelical United  
Church of Christ. Pres.

ART GLASS CRAFTERS  
Leaded & Stained Glass Windows  
16908 York Rd., Hereford  
MONKTON, P. O., MD 21111  
(301) 357-8255

PROPOSAL SUBMITTED TO <b>MR. TIERK</b>	DATE <b>DEC 22, 1978</b>
ADDRESS <b>1/2 EAST of Dillon Baltimore</b>	PHONE
JOB NAME AND LOCATION <b>UNITED EVANG. CHUR. of Christ</b>	ARCHITECT <b>MRS. Shechta</b>
<b>EAST of Dillon 21224</b>	JOB PHONE <b>276-0393</b>

We hereby submit specifications and estimates, subject to all terms and conditions as set forth on both sides, as follows:

REPLACEMENT of DAMAGED  
STORM Glass  
SIZE 41 X 69 1/2" 1/4 Plate (factory like)  
REPAIR to STAINED Glass Window  
1pc Blue Glass (Aobk) 11 X 13"  
1pc BROWN - 1pc plating 5 X 10"  
1pc Wire - color - Cracked - lead up

(Read Reverse Side)

We propose hereby to furnish material and labor — complete in accordance with above specifications.

for the sum of: **five hundred & thirteen 85** dollars (\$ **513.85**)

**20% Deposite - Balance due on completion**

Note: This proposal may be withdrawn by us if

not accepted within **90** days. Authorized Signature **[Signature]**

Accepted: The above prices, specifications and conditions are satisfactory and are hereby accepted. You are authorized to do the work as specified. Payment will be made as outlined above.

Signature **[Signature]**

Date **April 20, 1979**

Signature **[Signature]**

**United Evangelical United Church of Christ**